


BLADE CHANGE CHECK


B

Blade and all components must be securely fastened to the spindle




L

Look to see that the blade moves freely and is correctly mounted




A

Always ensure the saw guard is retracting properly




D

Double-check that all components are reassembled correctly



E

Ensure the machine runs smoothly before any cutting operations



S

Safety needs evidence — use a checklist and note any concerns

